

the fabricator.

Brazing copper tubing

It's simpler than it seems

By **Walter J. Sperko, P.E.**


Torch brazing copper tubing is one of the most common—but widely misunderstood—joining processes. It's possible to make sound joints that are just as strong as the copper tube, easier to braze, and less expensive to produce. But first you have to know basic brazing concepts, including joint design, filler metal behavior, and metallurgy.

Strength of Tube Joints

Butt joints between copper tubes can be just as strong as the copper itself if the filler metal is strong enough. This is because all of the load must be carried through the contact area of the two small surfaces at the ends of each piece (see **Figure 1**). Butt joints typically aren't used to join copper tube because maintaining alignment during brazing is difficult.

Socket joints, on the other hand, are self-aligning during assembly and brazing. In a socket joint, the filler metal doesn't have to be as strong as the copper because the contact area between the tube and socket can be made large (see **Figure 2**).

When the bonding area is large, the stress in the braze metal is low, so the filler metal can be much weaker than the base metal. Therefore, when you use commercial copper tube fittings that have deep cups, you can use soft solders with tensile strength of about 5,000 pounds per square inch (psi) successfully to join stronger cop-



This tool modifies copper fittings by making a shallow impression in the fitting wall, shortening the socket depth to $\frac{3}{8}$ in. It should be used only for joints that will be brazed.




Figure 1

Butt joints between copper tubes can be as strong as the copper itself if the filler metal is strong enough to carry a load through the contact area of the two small surfaces at the ends of each piece.




Figure 2

In a socket joint, the filler metal doesn't have to be as strong as the copper because the contact area between the tube and socket can be made large.

per tube with a tensile strength around 30,000 psi, for example.

Socket-joint Design

A tube joint has to be strong enough to carry loads such as pressure, dead weight, and thermal expansion. If you choose a combination of filler metal and socket depth that makes the joint stronger than the tube, the tube itself becomes the limiting factor in the design.

The strength of a torch-brazed socket joint depends on:

- Length of the overlap (usually the socket depth).
- Filler metal strength.
- Joint soundness.

Using these variables, you can estimate the required depth of insertion with this formula:

$$X = TW/0.8L$$

Where:

X = required overlap

T = tensile strength of the base metal

L = shear strength of the braze metal or solder

W = thickness of the thinner member

0.8 = soundness (or safety) factor

When you solder a copper-to-copper joint, the tensile strength of the copper is about 30,000 psi, and the shear strength of the solder is about 5,000 psi. For tube that is 0.065 in. thick, the overlap needs to be 0.48 in., or 8.7 times¹ the tube thickness.

When you braze a copper-to-copper joint with any of the commonly used AWS classifications of brazing filler metals, such as BCuP or BAg, the shear strength of the braze metal is about 25,000 psi. For a tube that is 0.065 in.




Figure 3

This chart plots the joint strength and shear stress to overlap length for soldered and brazed joints.

thick, the overlap needs to be 0.100 in., or 1.5 times the thickness of the tube.

The relationship between tube thickness and overlap length for brazed and soldered joints are plotted in **Figure 3**.

Brazing Overlap

To see if theory worked in practice, the author's associates brazed and performed tensile tests on 1½-in. copper tube with a wall thickness of 0.045 in. Joints tested were a butt joint and socket joints with overlaps of one, two, and three times the tube thickness. All specimens, including the butt joint, failed in the base metal.

It isn't news that you need only a small overlap for brazed joints. In a round-robin series of tests in the late 1950s, 10 labs brazed more than 1,200 tensile test specimens. The labs performed these tests on the following with various overlaps:

- 410 stainless steel furnace-brazed with BNi-1
- Mild steel furnace-brazed with copper
- Copper torch-brazed with BAg-1
- Mild steel torch-brazed with BAg-1

The results of these tests showed that you don't need a lot of overlap to get a full-strength joint. In all cases, base metal tensile strength was reached when the overlap was twice the thickness of the members (2t). The report was published as American Welding Society (AWS) C3.1-63.

The Downside of Overlap

The depth of insertion affects two significant aspects of brazing: the strength of the joint and the ease of brazing it. Although it appears from a strength viewpoint that more overlap is better, overlap beyond two times the thickness of the thinner member (2t) doesn't make the

Grade	Silver	Phosphorus	Zinc	Copper	Solidus, °F	Liquidus, °F	Span, °F
BCuP-3	5%	6%	•	89	1,190	1,490	300
BCuP-4	6%	7.3%	•	86.7	1,190	1,325	135
BCuP-5	15%	5%	•	80	1,190	1,475	285
BCuP-6	2%	7%	•	91	1,190	1,450	260
BCuP-7	5%	6.7%	•	88.3	1,190	1,420	230
BAG-7	56%	•	17%	27	1,145	1,205	60

*Indicates not added.

Figure 4

This chart shows common copper-based brazing filler metal composition and melting characteristics.

joint any stronger.

In fact, increasing the overlap much more than 2t only makes it harder for you to make a sound joint for the following reasons.

First, the braze metal has to flow uniformly into a small gap between the parts for the entire length and circumference of the joint. One obstacle is that the longer the overlap is, the farther the braze metal has to flow and the more opportunity it has to trap gas, which causes voids in the joint. A sufficient supply of flux and adequately high, uniform heating of the joint promote the flow of the braze metal into the joint, but as overlap increases and the diameter becomes larger, this becomes more difficult.

Second, brazing filler metal begins to melt at a lower temperature than the temperature at which braze metal is fully liquid. This temperature is called the solidus temperature. Just above this temperature, the braze filler is a mixture of solid plus liquid. It is thick and slushy, much like a frozen drink. In this condition, metal doesn't flow easily into a closely fitted joint. Imagine sipping a frozen drink through a small straw quickly — it's difficult!

As the filler metal is heated more, it becomes more completely liquid until it reaches the liquidus temperature. At this temperature, the filler metal is fully liquid and flows readily into the tiny space between the parts. Or, as with our example, the frozen drink now is melted and flows through the small straw easily. Solidus and liquidus temperatures for some common filler metals are shown in **Figure 4**.

To further complicate the situation, during brazing a small amount of the copper base metal dissolves into the filler metal, and a small amount of the alloying elements in the filler metal diffuse into the copper base metal. When this happens, the chemical makeup of the filler

metal changes. This increases the liquidus temperature, and the filler metal turns thick and slushy even though it's hot. Again, thick, slushy filler metal doesn't flow into the joint easily.

Fortunately, this diffusion-dissolution process is slow compared to the time it takes for braze metal to flow into a properly heated joint. However, if the joint isn't heated enough before

braze metal is introduced, the braze metal starts out slushy and becomes thicker as you reheat the joint. The longer the joint is at brazing temperature, the more the braze metal composition becomes like the copper itself. This explains why it can be difficult to get a joint to remelt after it's been brazed.

Diffusion isn't all bad, though. Jet engine compressors, for example, are used at temperatures above the melting temperature of the braze metal that holds them together. In this application, the parts are held in a furnace at diffusion temperature for so long that the braze metal is dissolved completely in the base metal and the joint is basically gone, allowing the engine to stay together in service.

Because fittings manufacturers have little control over where their fittings will be used or how they will be joined, the least risky thing for them to do is to make all the fittings suitable for soldering.

Using Solder-joint Fittings When Brazing

If excessive overlap makes getting a sound brazed joint unnecessarily difficult, why does the industry use solder-joint fittings that have so much overlap?

The answer is simple: lawyers. Ordinary copper and brass fittings are made to be soldered, not brazed. They typically give you 10t overlap or more, which is what is needed to ensure adequate strength if the joint is made with solder (see **Figure 5**).

Because fittings manufacturers have little control over where their fittings will be used or how they will be joined, the least risky thing for them to do—this is where the lawyers come in—is to make all the fittings suitable for soldering.

Solder-joint fittings can be brazed, but the cup depth can make your life difficult. Fittings with short cups that are designed for brazing are available and are easier to braze than solder-joint fittings, but they typically are special-order items with limited distribution. Contractors who supply the fittings to their craftsmen face the same liability risks as fittings manufacturers.

Qualification of Procedures and Brazers

When you qualify a Brazing Procedure Specification (BPS) under ASME Section IX, the minimum overlap that will be used in production must be used during qualification. In other words, if the overlap used on the test coupon was $\frac{1}{4}$ in., the minimum overlap that must be used in production is $\frac{1}{4}$ in. You also should be sure that the production overlap is at least twice the thickness of the thinner part to be joined ($2t$). This ensures adequate joint strength for production joints.

When you qualify a torch brazer, he or she is limited to the overlap that was used on the test coupon, plus 25 percent. In other words, if the test coupon overlap was $\frac{1}{2}$ in., the maximum overlap qualified is $\frac{3}{8}$ in. You don't have a minimum overlap, because if you can properly braze a deep socket, you also can braze a shallower socket.

Making Life Easier When Brazing

Because you need only a small overlap ($2t$) to achieve full strength in a brazed joint, you don't need the full depth of a solder-joint fitting. More socket depth just adds to your suffering when you're making a joint. To make matters worse, the bigger the tube diameter, the deeper the socket and the more difficult the joint is to make.

Several things can be done, especially with larger fittings, to make your life easier.

- Buy braze-joint fittings. These aren't readily available commercially.
- Have a machine shop trim the excess. This works, but it is expensive.
- Trim the excess cup in the field. This is prohibitively expensive and probably will result in distorted fittings.
- Fit the pipe into the tube with a short overlap. Although this works, it's difficult to control because the tube is free to move in and out of the socket during assembly.

Pipe Size	Solder-joint Socket Depth ¹	Brazed-joint Socket Depth ²	Percent of Braze Metal Saved Using $\frac{3}{8}$ in. overlap ³
$\frac{1}{4}$	0.31	0.17	N/A
$\frac{3}{8}$	0.38	0.20	N/A
$\frac{1}{2}$	0.50	0.22	24
$\frac{3}{4}$	0.62	0.25	37
1	0.75	0.28	48
1 $\frac{1}{4}$	0.97	0.31	59
1 $\frac{1}{2}$	1.09	0.34	63
2	1.34	0.40	69
2 $\frac{1}{2}$	1.47	0.47	71
3	1.66	0.53	73
3 $\frac{1}{2}$	1.91	0.59	75
4	2.16	0.64	77
5	2.66	0.73	79
6	3.09	0.83	81

¹ Based on ANSI B16.22.

² Based on MSSSP73 for type L copper.

³ Compared to solder-joint fittings. Includes allowance for full fillets on both ends of the joint.

Figure 5

This table shows the socket depth for solder and braze joint fittings and savings using a $\frac{3}{8}$ -in.-deep socket.

- Deform the fitting near the end using a tool such as that shown in the **introductory photo**. This tool limits the depth of insertion to $\frac{3}{8}$ in. and provides a positive tube stop so you can maintain proper insertion depth easily. ■

Walter J. Sperko, P.E., is an engineering consultant who specializes in welding and brazing technology with expertise in piping. He can be reached at Sperko Engineering Services Inc., 4803 Archwood Drive, Greensboro, NC 27406-9795, 336-674-0600, fax 336-674-0202, sperko@asme.org, www.sperkoengineering.com.

Note

1. Because solder creeps at ambient temperature, solder-joint fittings actually are designed on a unit stress of 235 PSI and are limited to maximum pressures at various temperatures in accordance with ASME B16.22. As a result, solder-joint fitting socket depths are $10t$ or more deep.

American Welding Society, 550 N.W. LeJeune Road, Miami, FL 33126, 800-443-9353, www.aws.org.

ASME International, Three Park Ave., New York, NY 10016, 800-843-2763, www.asme.org.

Phil Gurrieri of Integrated Mechanical Services, Plymouth Meeting, Pa., and Mike Lang, United Association Local 501, Aurora, Ill., helped prepare test specimens for the information in this article.